

# LOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Port AUCKLAND. N.Z.

18th. February 1960.

## This is to Certify that

A. HUNTINGFORD

undersigned Surveyor to this Society did at the request of  
ers Representative, attend on board the S.S. "MONOWAI" 11037 tons gross  
ington, while afloat at this Port on the 17th February 1960 and subsequently  
purpose of ascertaining the nature and extent of Damage stated to have  
d on the 17th February 1960 at Princes wharf, Auckland while berthing ship,  
contact with wharf.

For further particulars see ship's Log Book.

Upon examination the following damage was found and repairs  
ended without prejudice to the Terms and Conditions of Insurance.

Damage confined to set in shell plates, starboard side amidships.

### FOUND

### RECOMMENDED

lates starboard L12, M12, M13,  
12 set in. 10 frames in way

That the set in section of set in shell  
plates L12, M12 & 13, N11 & 12 be cropped  
and renewed.

knees in way buckled.  
rivets at L strake and M strake  
and M & N strake landings  
Frame shell rivets sprung in

That the buckled frames be cropped and  
renewed or cropped, faired and refitted.  
That the buckled beam knees be removed,  
faired and refitted.

scuttles in way of set in plat-  
kled and glass fractured.

That the buckled side scuttle frames and  
glasses be renewed.

The following temporary repairs have now been carried out:-

ung rivets and seams in way of set in shell plates and frames now sealed  
ng. Buckled beam knees faired in place and welded to frames.  
de scuttles in way blanked off and welded.

On completion the temporary repairs were hose tested and proved

It is recommended that permanent repairs be carried out at the  
Docking, but not later than the end of June 1960.

*A. Huntingford*  
A. HUNTINGFORD.

issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly  
is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances  
be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any  
Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of  
ees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

003971-003979-0097