

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

ENLT

10th March, 1925.

Transverse No. 18931 Depth "d" 16-33
Framing: Table No. Description Bulb angle frame with

Dear Sir,

With reference to Greenock report No. 18307 on the hull and machinery of the new steamer "RAZMAK", I have to acquaint you that the Committee have had the case of this vessel before them to-day, together with further reports from the Society's Surveyors at Belfast, and the vessel has been classed 100 A1, with freeboard, with notations of Fitted for oil fuel 2.25 F.P. above 150° F., Lloyd's A & CP, LMC 2.25, FD, CL.

It is concluded that the reversed frames and the vertical struts in the double bottom tanks are of bulb angles, but I shall be glad if you will kindly ascertain from the Surveyors and let me know whether this is so.

I am, Dear Sir,

Yours faithfully,

Assistant to the Secretary.

The Secretary,

GLASGOW.



© 2021

Lloyd's Register Foundation

003971-003974-0103

It is concluded the reversed frames of the double bottom tanks are of bulb angles but the Surveyors should be requested to state if