

2 of Bolinder Munkster

Engines Nos. 34741-42  
and 34743-44

Plan. 5628

" 5629

It is submitted the Plan Surveyors be  
told that in earlier engines of this size  
thickness of the outer crankwebs was 45 mm.  
that of the inner webs 50 mm. In the  
absence of any plan for the present engines  
should be asked to state whether 40 mm.  
the thickness of the outer webs and <sup>confirm that</sup> ~~webs~~  
is in accordance with the approved plan.  
They should also give the thickness of the ~~outer~~  
inner web.

They should also state whether the  
engines are to be started by means of  
compressed air, and if so, they should state  
what arrangements have been made to fit  
the valves on the cylinders.

Chas L. Sker  
21/5/43

© 2021

17/5/43.

Lloyd's Register  
Foundation

003971-009419-0358