

S
A
N
D
D
I
V
E
R

WRECK
SECTION
No. 948

WRECKED

J	J
F	F
I	M
A	A

M	M
JE	JE
JY	JY
A	A
S	S
O	O
N	N
D	D



© 2021

Lloyd's Register
Foundation

003980-003984-0001

531063	SAND DIVER	379	SS *	SS 3/62	1944-12	Henry Scarr Ltd.—Hessle	M Sand Suction Dredger	Mchy.aft	Oil 4SA 7Cy. 220 x 290 mm sr gear	231
MC6B	exBraywick-53 exRiver Ouse-52	175	sand carrier	Bristol	148' 2" 27' 2" 9' 3 1/2"		1 Ho 53 1/2'		280bhp	231
180391	exEmpire Farrier-47	403	Channel & South of	England coasting service	141' 0" 27' 0" 11' 0"		G.2502		Blackstone & Co. Ltd.	231
Esd RT	South Coast Shipping Co.		including Thames Estuary		P38' F14' Trunk 82' 1 dk					231
	Ltd.		ary		4BH	conv cargo ship 53	1W			231
	London	British			WB166t					231
			MBS*							231
			MN50	CT398 C18						231

LAST SPECIAL SURVEY		HULL				MCHY.					
		362					362				
LAST DOCKING SURVEY		363	264	10.64	4.65	10.65	4.66				
„ BOILER „		/	/	/							
„ AUX/DONKEY BLR „		/	/	/							
„ STM. GEN. „		/	/	/							
„ SCREWSHAFT		OG	162	4.65							
„ STEAMPIPS „		/	/	/							
„ WEAR DOWN ON STERN BUSH		Not taken.	TIGHT	NOT TAKEN	.060"	N.T.	tight				

Quint.

SS pp. 3.67