

EA

12 MAR 1965

Ship's name "SAND DIVER"

Port

SOU

No. 29428

Class is subject to

Last survey date 26.2.65.

NONE.

S.R.L. Appendix (as before or none)

XXXXXXXXXXXX

Nature of present survey (afloat and in drydock)

XXXXXXXXXXXXXXXXXXXX

Temporary repairs to wasted shellplate
in way of F.P. tank.

Recommendation

SUBJECT to wasted bottom shell plate in way
of F.P. tank suction (p.s) being specially
examined and dealt with as necessary next
drydocking.

As Now Subject.



© 2021 *ssd*
12/3/65

Lloyd's Register
Foundation