

MEMORANDUM

From : LLOYD'S REGISTER OF SHIPPING,

71, FENCHURCH STREET,
LONDON, E.C.3.

(Ref. R.)

To : The Surveyor(s) at SOUTHAMPTON

Date: 15th December, 1964.

Vessel's Name:

m.dredger "SAND DIVER"


SEI/SO

19 JAN 1965

QUESTION

Screwshaft Survey due 1.65.

Reference Entry for vessel in your Weekly Return dated the 2nd October, it is concluded the dredger is still under survey at your Port, in the absence of any further Entry in your subsequent 5b Returns, and I shall be glad to learn what is the position regarding the Screwshaft Survey.




ANSWER

Date:— 6th January, 1965.

It is regretted that submission of our report on the October docking of this ship was overlooked.

The Owners, questioned regarding the Screwshaft Survey, stated that the ship would again be drydocked in March next, and proposed withdrawing the shaft for Survey at that time. They trust this will be acceptable.



© 2021

Lloyd's Register
Foundation

003980-003984-0036

R