

26 APR 1963

Ship's name "SAND DIVER"

Port

SOU

No. 28098

Last survey date 11.3.63

Class is subject to

Metallock repair to gear box being re-examined by 3.63  
(1 year limit).

---

Docking, wear-down not taken.

SRL item

Main engine gear box now specially examined in way of metallock repair and at this time found to be satisfactory. Surveyor submits that this item may now be deleted from the SR list and suitable note entered in the SRL appendix.

IT IS SUBMITTED that this vessel is eligible to remain as classed without special condition.

SRL appendix to note:

Main engine gear box metallock repaired.



© 2021

23.4.63

Lloyd's Register  
Foundation