

50

Boilers, when made (Main) ✓
Owners "ZINAL" S.S. Co Ltd. (Donkey) ✓
Owners' Address ✓

COPY

12 FEB 1953

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port SOUTHAMPTON.

30th January, 1953.

"BRAYWICK"

REPORT

This is to Certify that I have

Surveyed the M.V. "BRAYWICK", 411 tons gross of London, as

the vessel lay on the Slip at Itchen, Southampton, on the

30th January, 1953, for Docking Survey, *as per*

SUBMITTED that this vessel is eligible to remain

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be retained as now classed

with fresh record of Survey 1,53, subject to:

Shell. Port side sheerstrake abreast after end of No. 1 Hatch being faired as necessary at next Special Survey.
Rudder. Bottom gudgeon being overhauled and stream line plate of stern post welding being overhauled as necessary by April, 1953,


being fit to carry dry and perishable cargoes.

E. Mustart

Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed. It is understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register for publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member Surveyors, or other Officers or Agents of the Society."

Om.1251. (MADE AND PRINTED IN ENGLAND.)



Lloyd's Register
Foundation

003980-003984-0060

's Minute

TUES. 24 FEB 1953

As now