

28 MAY 1964

Ship's name "ASTON VILLA" Port GMS No. 30205
Class is subject to NIL Last survey date 18.4.64.

Two fractures found in H.P. cylinder foot (p.s.), now repaired by metalock. Main Engine tested under working conditions and found satisfactory. Surveyor recommends metalock repairs (4.64) to Main Engine H.P. cylinder and foot (p.s.) be again examined before the end of September, 1964.

IT IS SUBMITTED that this vessel is eligible to remain as classed, subject as now recommended.



¹⁰⁰
© 2020
27.5.64.

Lloyd's Register
Foundation