

6m, 10, 59

Class is subject to

4E

31 MAR 1960

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME LOUIS LANTZ

REPORT EMD.

No. 319

CS advanced

Repairs. Port ME N° 5 and Starboard ME N° 7  
cylinder covers renewed

Steering engine starboard cylinder cracked at  
bottom and repaired by Metatech  
and spare bearings for crankshaft fitted

The Surveyor recommends the steering engine  
cylinder be specially examined by 11,600  
(9 months limit) metatech repair

It is submitted that this  
vessel is eligible to remain  
as **CLASSED**. *subject as new*



© 2020

Lloyd's Register  
Foundation

004055-004061-0082