


"SKOTAAS" - Amsterdam Report 18445

After further consideration of this case it
mitted the Owners should, in the first instance,
ised that following the special examination
structure held recently at Amsterdam, the
as now been specially investigated, and it is
ered that two girders should be fitted to the
for details see attached endorsement) as
as possible, and the Committee would be glad
informed when the Owner could arrange for this
done.

Further, it is not considered essential to
ditional stiffening to the bottom at this time.


26th September, 1952.



© 2020

Lloyd's Register
Foundation

004055-004061-0171