

## LLOYD'S REGISTER OF SHIPPING



Åbo

Port

31st December, 1958

This is to Certify that I have  
 Surveyed the Machinery of the s/s "LEDSUND" 3955 tons gross of  
 Marienhamn in Drydock at Åbo 28.11.58 and subsequently for  
 MBS and Damage stated to have been caused by heavy ice during  
 the voyage commencing 7th July at Blyth to Igarka and thence  
 to Finland, and for General Examination for postponem. of SS due  
 and that I will transmit to the Committee of Lloyd's Register of  
 Shipping, London, a Report stating that all recommendations made by  
 me in connection therewith have been carried out to my satisfaction; also  
 that I will Recommend that in the case of this Vessel the following  
 Survey Records be made in the Supplement to the Register Book  
 MBS 11.58 when the survey has been completed and I  
 recommend the Special Survey due 12.58 to be held not later  
 than Dec. 59  
 and that her Machinery Classification Record be continued in the Book.  
 To complete MBS: Safety valves of port Main Boiler remain  
 to be adjusted.

Parts now examined:  
 (C.S. Items only)

Åke Lindqvist.

Engineer Surveyor to Lloyd's Register.

## KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Pitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."