

2 FEB 1954 E

by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

NAME..... LEDSUND..... REPORT..... Abo..... No. 112.....

MBS due 11.58 part held now.

Damage stated due to encountering ice, a propeller blade found fractured and spare blade fitted.

A general examination carried out for postponement of Special Survey.

IT IS SUBMITTED that this vessel WILL BE eligible for the record MBS 12.58 on completion as this report, and the proposal to postpone Special Survey until 12.59 merits approval.



*Ews*

28.1.59. © 2020



Lloyd's Register  
Foundation

004062-004066-0089