

S.S. "HESPERIA" ex "PATRIA"

It is regretted that this question of equipment was not raised earlier, but seeing that the bower anchors ~~are~~ of the Gruson-Hein type, a type which the Committee in June 1920 decided could not be approved on the ground that the base of anchor and the flukes were not considered satisfactory, it is still considered that these anchors should be replaced by others of equal weight and approved pattern within a reasonable time, and as may be convenient.

It is submitted the Liverpool Secretary be informed as above, and asked to advise the Owners of the vessel intimating why the Committee have not approved this type of anchor.

Spe

GA

A.Y.A.

8. 8. 21.



© 2020

Lloyd's Register
Foundation

004062-004066-0105