

COPY

off. no. 62806

LLOYD'S REGISTER OF SHIPPING



Port..... CARDIFF.

Date..... 25th September, 1965.

This is to Certify that I have surveyed part of the machinery of the M.S. "M. MYRTIDOTISSA", 5103 gross tons of Beirut whilst afloat at Cardiff on 8th September, 1965 and **for** subsequently for continuous survey of machinery and damage alleged sustained by heavy weather while on passage from Archangel to Cardiff,

and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following

survey records assigned CSM (with date) when the survey has been completed subject to the windlass gypsies, main gear wheel and pinion being renewed by 10.65 as previously recommended and to any outstanding conditions of class being dealt with as previously recommended.

Parts now examined:—

All main engine side rod glands.
No. 1 main engine cylinder, pistons, rods, transverse beams and bottle guides, valves and gears.
Main engine thrust block, shaft and bearings.
Auxiliary condenser (tested).
Main engine holding down bolts and checks.

E. H. Barlt.

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

| | | | | | |
|-----|--------------------------------|-----|---|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey | MBS | Main Boiler Survey | TS | Tailshaft Survey |
| CSM | Continuous Survey of Machinery | OF | Fitted for oil fuel (date) FP above 150° F. | TS(CL) | Tailshaft Survey—Continuous Liner |
| DBS | Donkey Boiler Survey | SGS | Steam Generator Survey | TSN | Tailshaft renewed |
| ES | Engine Special Survey | SPS | Steampipe Survey | TS(OG) | Tailshaft Survey—Oil Gland |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society."