

22nd August, 1958.

HAMBURG

6668, 702, 10, 15 - As recommended.

RMC.6664, 702 - As recommended.

6659 "BENMHOR" As recommended, except that the notation of SS Lon. 2,58 has been withheld pending the completion of the Engine Survey.

6708 "MORCHELLA" As recommended. It is concluded that the safety valves were placed in a satisfactory condition before adjustment, but your confirmation is desired.



© 2020

Lloyd's Register
Foundation

004076-004083-0162