

12 AUG 1965

Ship's name PAKISTAN PROSPERITY Port KRW

No. 863

Class is subject to

Last survey date

26-6-65

- 1 CENTRE BOILER NOT BEING USED UNTIL REPAIRED
- 2 G.S. PUMP STEAM CYLINDER CHEST BEING RE-EXAMINED BY 1.65

SUBJECT ITEM 2, EXAMINED & SURVEYOR CONSIDERS
EFFICIENT FOR FURTHER PERIOD UNTIL 12.65

MBS DUE 5.65 HELD.

A NUMBER OF DEFECTIVE PLAIN & STAY TUBES WERE FOUND
IN STARBOY BOILER CENTRE TUBE NEST & CENTRE FURNACE
DISTORTED & REPAIRED BY PATCH WELDING PREVIOUSLY. PLAIN
TUBES HAVE BEEN RENEWED & 6 STAY TUBES STOPPED
THE FURNACE DISTORTION WAS NOT DEALT WITH & SURVEYOR
RECOMMENDS

- 1 DEFECTIVE & SEAL WELDED STAY TUBES IN STARBOY BOILER CENTRE
TUBE NEST BEING RENEWED ON ARRIVAL CHITTA GONG WHERE NOW
BOUND BY 7.65
- 2 STARBOY BOILER CENTRE FURNACE (DISTORTED & R.W. REQUIRED)
BEING EXAMINED & DEALT WITH AS FOUND NECESSARY BY 9.65

C.S. Advanced.

It is submitted that this
case is eligible to remain
as **CLASSED**. SUBJECT AS

ABOVE ITEM 1, AND AS AMENDED
ITEM 2 TO LIMIT DATE 12.65. &
AS NOW RECOMMENDED

THE RECORD OF MBS 6.65
DEFERRED FOR SUBJECT ITEMS
1 & 2 NOW RECOMMENDED BEING
DEALT WITH.

004076-004083-0207