

2

49-70

Port San Diego

March 5 1949

Survey held*

Owners Kent Line Ltd., of St. John, N. B. Electric Lighting? Kws.

Engines: _____
Description _____ Made by _____ When _____

Cylinders. No. each Eng. Diars. Stroke Cub. Ft. each L.P. Cyl.

Suppliers:			
Item	No. & Description	W.P.	Made by
			When

ux. M.
onkey Do. W.P. Made by When

ain Steam Pipes, Material..... Welded, Brazed, Seamless..... When Tested.....

Propeller Shaft, Diam. under Liner..... Description of Liner..... When Drawn.....

ISS **M. B. S.**..... S. S. No. Due Boiler Survey Due M.S. Due

* Insert name of Dry Dock; or where, if afloat

Repairs made at San Diego Marine Construction Co., San Diego, California.

Estimated cost of repairs - \$1,500

NOOT.
DEPT.

Visit Feb. 17, 1949 Last Visit March 3, 1949 Boilers and Engines then in Good Condition

of Visits 4

xx \$50.00

Advised.....


enses \$2.00

Paid.....

~~xx~~ \$52.00

Surveyor to the British Corporation Register
of Shipping and Aircraft

Chief Surveyor



© 2020

Lloyd's Register
4092-0050
Foundation