

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

1st February, 1960

en. (S)
W/KL

Dear Sir,

Steamer "GUAM PIONEER"

As a result of a survey carried out at Balbao in October, 1959, the Surveyor issued a Rpt. 10 stating that the spare anchor and two lengths of wire rope had been lost.

It is noted from San Francisco Rpt. No.11326 that the Surveyor has stated there are three bower anchors now on board, and I shall be obliged if you will request the Surveyor to confirm that this is correct, as there is no information in this Office regarding the supply of a bower anchor since October, 1959.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Secretary,
NEW YORK.



© 2020

Lloyd's Register
Foundation

004084-004092-0206