

Frames from centre to centre amidships from  $\frac{3}{8}$ "

28 28

KEELSONS AND STRINGERS.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Stal S.S. ABODI-MENDI*

Rpt. *Hal*

No. *11059*

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

*Before this case receives consideration the report should be returned to the Surveyor who should be requested to fill in the particulars of the Chain Cables Supplied*

*See letter 22.5.21*

*v. Mdb. 22nd*



© 2020

Lloyd's Register Foundation

004093-004100-0035

Along or Shltr Dk, Single Angle, 9" 3 1/2" x 42"

„ Tie Plates, outside Hatchways .....