



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Bank Chambers, 2, Freeman Street, Grimsby

Telephone No. 3156

2nd August 1961.

RECEIVED

4-AUG 1961

Ans'd.....

Reference

Dear Sir,

"NORTHERN DAWN"

With reference to your letter dated 27th July, I regret that I cannot recommend that the present Condition of Class attached to the stern frame, be deleted. The repair, while apparently sound, still showed signs of possible grooving and it is submitted that a further period under observation would be desirable.

Yours faithfully,
The Surveyors,

The Secretary,
LONDON.E.C.3.



© 2020

Lloyd's Register
Foundation

004093-004100-0080

004093-004100-0081

AIR

SR- REPORTS

noted, *ML* G.O. 4/8/61

LONDON: E.C.3.
The Secretariat,

99x-97

The enclosed,
London 19/11/61

would be desirable.
submitted that a further letter under observation
should be signed by Messrs. Gillingham and if it
referred. The letter, while still in the hands of
Commission of Steel attached to the steel works. It
I think that I cannot recommend that the enclosed
with reference to your letter dated 22/11/61.

ANTHONY DUNN

Dec 11,

4-100/61

RECEIVED

2nd August 1961

Bank Chambers, 3, Finsbury Street, London

FILED WITH THE BRITISH CONSOLIDATION REGISTER

LLOYD'S REGISTER OF SHIPPING

© 2020

Lloyd's Register
Foundation

