

24 JUL 1961

Received from Chief Ship Surveyor.....

SHIP NAME "NORTHERN DAWN" REPORT GMS No. 28808

EA

Standing Conditions of Class: SUBJECT to sternframe (E.W.3,59) being specially examined next drydocking.

Appendix. ~~(As before)~~ None

Result of Present Survey: (Afloat and in dry dock)

Docking:- Minor repairs.

Recommendation: SUBMITTED record of DS 6,61 be assigned, subject as above.

DS 6,61 Subject.

IT IS FURTHER SUBMITTED the Surveyors be requested to advise whether the condition of class regarding the sternframe can now be deleted, in view of its satisfactory condition over a period of 2 years, (refer Circ. No. 3707A).

See letter dated 2/8/61

© 2020



Lloyd's Register Foundation

Handwritten signature and date 14/11/61