

00416-004124-0088

4 E

d by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME

Lucerna.

Rpt.

Mch.

No.

10517

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

e of Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH *enemy action*

Port engines examined. Aylfiner Cover & skirt broken removed. Cargo pump removed on large number of cargo valves broken removed. Together with piping Cargo heating piping removed. & minor repairs & adjustments to auxiliary

Subject to the Spf.

OBS held Y.S. examined

C.S. advanced.

Under date. 4.41

It is submitted that
this vessel is eligible for
THE RECORD.

S. H. 40

Without special
Condition~~STEAM~~ BOILER

Not being used

OBS

4.41

Y.S.

6.6.41

Lloyd's Register
Foundation