

Monte Navajo *

F.E.

Received Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL NAME *M. S. Ariz Mendiz* Rpt. *Bbo.* No. *5668*

The acts of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.

Traverse No. *84-48*

Depth "d" *27-7 1/2*

Frang: Table No. *3*

Description *Bulb angles reversed frames*

Loitudinal No. *33791*

Proportions Length = *10.47*
Depth =

ridge Deck Sheerstrake *as approved.*



This vessel appears to have been built in accordance with the Rule and the approved plans, and it is submitted she is eligible to be classed


✱ *100A1 (Steel) as recommended.*

1 Dk. Mt.

Cell DB. 351' 1103t. F.P.T. 145t. A.P.T. 142t.

F.K. 6BH. Cem. Lloyds A.P.P. P.40' B.115' F.38'.

M.D.
17.10.20.



© 2021

Lloyd's Register Foundation

004170-004176-0131

Dry Dock
o. of Dec
o. of Tie
Round
Dk. Be
Inches
size in
Ship.
No. 31
12 x 3 1/2
5 x 3 x 3
2000
Inches
Ship
1000
x 3 x
44
x 3 1/2
62 to
rease
5 x 66
10 to
38
66
36
3 1/2
54
49 to
35 x 36
3 1/2 x 3 1/2
18 x
5 x