

COPY

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: Royal 3551 (4 Lines)

WRECK  
SECTION  
No. 895

2nd August, 1951.

Classen.  
(S)

N/R P

Dear Sirs,

S.S. "ARGENTINA"

The Society's Surveyors at Hong Kong have forwarded to this Office a letter from your Agents in that port, in which it is stated that, as this vessel is under the American Bureau Register, the attendance of a Lloyd's Surveyor on board is therefore not required.

In the circumstances the Committee, who have recently had this case under consideration, have given instructions for the vessel's class to be withdrawn from the Society's Register Book and a notation of "S.S. - Class Withdrawn" inserted in thereof, indicating withdrawal of class at Owners request.

Yours faithfully,

BROKEN UP  
R/B 1952/53

Copies sent H.Kg

Clerk to the  
Classification Com

Messrs.  
John Livanos & Sons, Ltd.,  
Stone House,  
Bishopsgate,  
E.C. 2.

004184-004193-0211



© 2021

Lloyd's Register  
Foundation