

N/N TEXAS RANGEN



17, BATTERY PLACE,

NEW YORK.

LLOYD'S REGISTER
Re
30 JUL 1937
Assd.
LOND

July 23, 1937.

Dear Mr. Hutchinson:

M/V "TEXAS SUN"
Phl. 7272

Referring to the inquiry contained in your letter of the 30th ultimo, regarding the above mentioned case, I am advised by the Surveyor that two seams of the side shell plating, i.e. the upper seam of "S" strake and the lower seam of "H" strake, were electrically welded as approved and indicated on the approved plan of midship section.

I am enclosing another set of test sheets relating to the Fusion Welded Boiler Drums and I am in communication with the Cleveland Surveyor regarding the dynamo test sheets.

With kind regards,

Yours faithfully,

R.P. Hutchinson, Esq.,

LONDON.



© 2020

Lloyd's Register
Foundation

004194-004199-0083

Referred to Mr. Sturden.

~~Referred to the Chief Engineer~~

~~Referred to Mr. Hill.~~

to await dynamo test sheet

Yours

30 JUL 1937

Mr. Ward
Ketchum

Revised 1937



© 2020

Lloyd's Register
Foundation

W/M TEST W/M

Insu

Purc