

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name SS/MS "ALTIS" (LR 501296) S.S. ( ) Due  
 Port MANILA Rpt. No. 1045

	<u>Examined &amp; condition</u>		<u>Examined &amp; condition</u>
In dry dock from	16/10/65	* Air & sounding pipes	Good
.. .. to	18/10/65	Doublers under .. ..	-
Shell plating	Good -	Steering arrangements (main)	-
Sternframe	"	.. .. (aux)	-
Rudder	"	Windlass	Good
Was rudder lifted?	No	Masts & rigging	-
Plating, etc. in way of shell openings	Good	Hand pumps & suction	-
Side scuttles & deadlights	"	W.T. doors	Good
Overbd. scuppers & discharges	"	Bulwarks, freeing ports, etc.	"
F.P. spaces	-	Summer freeboard as verified	-
Chain locker	-		
A.P. spaces	-		
Engine space	Good		
Boiler space	None	<u>EQUIPMENT:</u>	
Under E. & B.	-	Equipment letter	
Coal bunker	None	Fee ltr., if diff. from eqpt. ltr.	
Tunnel & well	Good	Anchor: No. on board	
Cement, asphalt, etc., on btm. shell	-	State if ranged	
Weather decks	Good	Length on board	
* Casings	"	Mean dias. range from	to
* Deckhouses	"	Rule length	Dia.
* Superstructures	"	Mooring ropes	
* Skylights	"		
* Companionways	"		
* Hatchways	"		
* Ventilators	"		
Other items:	-		

\* These items to include their closing appliances  
 Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2020  
 C. RITCHIE

Surveyor to Lloyd's Register of Shipping  
 Foundation

004194-004199-0360

HOLDS & 'TWEEN DECKS:	Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	Ship Loaded	F.P. tank	
..	'Tween decks		A.P. tank	
			D.B. tanks & c/dams	
			Nos. 2 & 6 (OF)	tested & proven tight
No. 2	Hold			
..	'Tween decks			
No. 3	Hold		O.F. bunkers	
..	'Tween decks			
			Settling tanks	
No. 4	Hold			
..	'Tween decks		Deep tanks	
No. 5	Hold			
..	'Tween decks		Side tanks	
No. 6	Hold		Wing tanks	
..	'Tween decks			
			Other tanks:	
	Cargo battens			
	Ceiling, etc.			



© 2020

Lloyd's Register Foundation