

Ship's name

"ALLURITY"

Port

Lon

25 JAN 1963

No.

148606

Last survey date 31.13.62

GB

Class is subject to indented shell plates D. 3 & 4 and
E. 3 & 4 (p & s.f.) being specially examined and dealt
with as necessary next drydocking.

S.R.L. Appendix (~~as before~~ or none)

Nature of present survey (afloat ~~and in drydock~~)

Temporary repairs on account of contact damage.

Recommendation

SUBJECT as above, and to stem and bow plating
being specially examined and dealt with as
necessary by the Special Survey.

As Now. Subject

ENGRS. SURVEYORS TO NOTE.

noted.

yes

25.1.63



© 2021

Lloyd's Register
Foundation