

COPY

LLOYD'S REGISTER OF SHIPPING




Port.....HONG KONG.....

.....28th November, 1964.....

This is to Certify that ^{we} I have surveyed part of the machinery of the S.S. "COSMO TRADER", 7201 Gross tons, of Hong Kong, for whilst in drydock and subsequently, on account of Damage stated due to grounding on Chau Kung Island, on the 5th September, 1964 during typhoon "Ruby",

and that all my recommendations have been carried out to my satisfaction. We
are reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned without fresh record of Survey, and subject to main and auxiliary machinery, Electrical Equipment and the Boilers, all being specially examined and dealt with as Parts now examined:— necessary before the ship leaves this Port, and to any outstanding conditions of class being dealt with as previously recommended.



(Signed) James I. Mathewson

for R.F. Zbinden, Surveyor, Lloyd's Register of Shipping

Surveyor, Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”

004206-004212-0054

© 2020 Lloyd's Register Foundation