

4 E

21 SEP 1949

d by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SE'S NAME

"BENOIL"

REPORT

Rot.

No. 31559

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

of Survey REPAIRS TO ENGINES AND-BOILERS DUE TO DAMAGE THROUGH grounding.

Screwshaft examined and found cracked at the forward end of the liner. Machinery partly opened up and some bearings remetalled and other minor repairs effected.

IT IS SUBMITTED that this vessel is eligible for the record S (N) 7.49.



© 2021

*TR*

Lloyd's Register  
Foundation

004213-004221-0445