

"EXAMINED L.R." 6.44.

27 MAR 1945

Surveyors.....

Received from Chief Surveyors.....

NAME "HALVARD BRATT" REPORT Liv. No. 122347

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

ses which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been  
quired and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case  
that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Damage. When done

Permanent repairs are required to indented shell plating  
(p.s) and to fractured stem plates etc. at the first convenient  
opportunity.

Rudder mainpiece, E.W. and reinforced 5.43, requires to be specially  
examined at the next dry docking.

(A bower anchor requires to be supplied).

  
26.3.45



© 2020

Lloyd's Register  
Foundation

004238-004248-0128