

V.

17 JUL 1944

and by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SEL'S NAME "HALVARD BRATT" REPORT Hul. No. 52489

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A notation of "Examined L.R. 5.43" has been assigned to this vessel.

For outstanding requirements see previous endorsement.

The HULL Surveyors now report this vessel placed in dry dock, bottom coated, a further GENERAL EXAMINATION made and minor repairs effected.

The outstanding items, as above, continue efficient.

IT IS SUBMITTED the vessel is worthy to have record of docking survey 6.44 and "Examined L.R. 6.44" valid for 12 months assigned as recommended. These notations are subject to permanent repairs being effected to indented shell plating (p.s.) and fractured stem plate at the first convenient opportunity and to rudder main piece E.W. and reinforced 5.43 being specially examined at the next dry docking and to (a bower anchor being supplied).

6.44 Hul. subject.

"Examined L.R. 6.44"

Amend S.R.L.



16.7.44 2020

Lloyd's Register
Foundation

004238-004248-0135