


COPY

Kobe Rpt. 8 No. 8258

## LLOYD'S REGISTER OF SHIPPING



Port

KOBÉ

Date

18th October, 1960.

This is to Certify that I have

Surveyed the S.S. "MOON" 2830 gross tons of Panama on the 9th September and subsequent dates whilst afloat and in dry dock at Mukaishima Japan on account of Docking, Annual Load Line & Damages stated to have been caused by (1) Contact with timbers whilst loading timbers at Tanbungan Harbour Mindanao, Philippine, on the 4th day of June, 1960. (2) Contact with timbers whilst loading timbers at Tanbungan Harbour Mindanao, Philippine on the 7th day of June, 1960. (3) Contact with timbers whilst loading timbers at Mati Harbour, Mindanao, Philippine on 10th day of June, 1960 (4) Contact with floating objects whilst on a voyage from Yokohama to Nagoya on the 1st day of September, 1960. (5) Loading timber cargo on shelter deck and that I will transmit to the Committee of Lloyd's Register of (P.T.O.)

Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, also that I will Recommend that she ~~be~~ remain as classed and have been record of dry docking 9,60 subject to set down shelter deck plating in way of Nos. 2 & 3 Hatches being specially examined and dealt with as necessary at Special Survey.

Blading, Bearings &amp; Thrust

TURBINE

MOTORS

AULIC CYLINDERS

WATER &amp; PUMPS

WATER &amp; PUMPS

WATER &amp; PUMPS

CONDENSERS, PUMPS &amp; VALVES

STEAM RE-HEATERS

SUPERHEATERS

STOP &amp; MANOEUVRE

AS Annual Survey  
B/S Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
SS(P) Hull Special Survey (Progressive)

## KEY TO ABBREVIATIONS

Surveyor to Lloyd's Register.

H. McLean.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B) 3,60 KOB

004257-004262-0025

TUESDAY 29 NOV 1960

Date of Committee