

COPY

LLOYD'S REGISTER OF SHIPPING



Port D U R B A N

Date 5th November, 1961.

This is to Certify that I have
 Surveyed the Steamship "SITHONIA", 7213 tons gross of London,
 whilst afloat at Durban, on the 5th November, 1961, on account of
 reported leakage at sanitary ship's side discharge valve chest covers in
 Nos. 2 and 4 tween decks and a refrigerator cooling water ship's side
 discharge valve chest cover in No. 3 lower hold, starboard side,

and that I will transmit to the Committee of Lloyd's
 Register of Shipping, London, a Report, stating that all repairs
 recommended by me have been completed to my satisfaction,
 also that I will Recommended that she be retained as at present
 classed without fresh record of survey.

NOW DONE: Leaking ship's side discharge valves in Nos. 2 and 4
 tween decks and No. 3 lower hold which had been repaired
 by the ship's staff examined and tested and found in order.
 The other ship's side discharge valves in these spaces
 examined and found in order.

(SIGNED) T. H. NOEL.

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BIS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	(SS)P	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."