

4E

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor - 6 AUG 1958

SHIP'S NAME..... WAVE EMPEROR..... REPORT Cff No. 60543

Damage due grounding.

Docking. Three blades of bronze propeller found somewhat damaged, not dealt with at this time and the Surveyor recommends the propeller be examined and dealt with as necessary next drydocking, considered efficient in the meantime.

SRL Appendix.



© 2020

5.8.58.

Lloyd's Register
Foundation

004275-004284-0187