

The class is subject to the main gear wheel and pinions
renewed at the first opportunity and being specially examined
57, main engine not to be operated at a speed in excess of
P.M, pending renewal of main wheel.

21 OCT 1957 4E

Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

E....."WAVE CONQUEROR".....

REPORT


~~N.YK.~~

No. 5230.

Curacao

SRL : The main engine gear wheel pinions specially
examined and found to be satisfactory in the meantime and the Surveyor
recommends the main engine gear wheel and pinions being re-examined
before the end of 3.58. Main engine not to be operated
in excess of 75. R.P.M.

IT IS SUBMITTED that this vessel is eligible to remain
CLASSED, subject as recommended.



© 2020

Lloyd's Register
Foundation

004275-004284-0241