

"EMPIRE PALADIN"

Rpt.Mdb.No.17701.

Before this case receives consideration it should be pointed out to the Surveyors that it appears from their report that a rudder with a forged main piece has been fitted in this vessel, while the approved plan forwarded by them shows a built up, electrically welded rudder without a forged main piece.

They should be requested to state whether the reported particulars are correct, and if so to forward the applicable approved plan for verification.

*[Handwritten signature]* *[Handwritten signature]*  
9.9.44.



© 2020

Lloyd's Register  
Foundation

004275-004284-0280

8



© 2020

Lloyd's Register  
Foundation

De Br L  
FR  
SID  
F  
R  
D  
F  
POM  
S  
PAY  
STI  
SIN  
F