

The class is subject to the boiler safety valves being adjusted and the oil burning arrangements being examined under working conditions before the vessel is placed in commission.

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

4
28 MAY 1957

NAME "ASSIDUOUS". REPORT Gib. No. 4054.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

SRL This item now dealt with.

IT IS SUBMITTED that this vessel is eligible to remain AS CLASSED, without special condition.

ADU
22.5.57.



© 2021

Lloyd's Register
Foundation

004292-004299-0379