

"BONITA"

IT IS SUBMITTED the Bremen Surveyors be informed in reply to their letter of 19. 7. 52:-

- 1) Copy of Owners' letter accepting a replace connecting rod which was tested by Norske Veritas does not appear to have reached this Office, neither has the Norske Veritas Certificate of 25.8.51. Please forward further copies.
- 2) Please state the nature and extent of defects found in two connecting rods, bearing in mind that this is the first intimation of any troubles with these parts.

It is concluded a Lloyd's-tested connecting rod was used for replacing the second rod.

*rec. 14/8/52.*

*Enk*



© 2020 8. 8. 52.

Lloyd's Register  
Foundation

004308-004315-0036