

Motorship "SUD"

This ship became due for Special Survey in 11.53 and postponement was granted by the Committee. In 8.54 the major part of this inspection was carried out but it was stated that due to the extent of repairs necessary to the boilers etc., it was possible that the ship would be broken up.

The ship remained laid up, and on 26.7.55 the Committee gave instructions for a notation of "Laid up - Surveys Overdue" to be recorded in the Register Book. (Note: In accordance with present practice this notation has now been amended to "Surveys Overdue 11.53)."

The case has been reviewed from time to time and the position has remained the same, but, in a memorandum dated 29.9.59 the Buenos Aires Surveyors stated that the ship had been sold and that the new Owners proposed to carry out extensive repairs and place the ship in service.

In reply to a further enquiry as to the position the Buenos Aires Surveyors now state that the ship underwent extensive repairs and is again in service, but that they were not called in. They add that no other Classification Society was concerned, and advanced the opinion that the Owners were not interested in Classification.

24th February, 1960.



Lloyd's Register
Foundation

004308-004315-0139

FRIDAY 26 FEB 1960

Non-compliance

bsh


GENERAL COMMITTEE

Thursday,

24th March, 1960

Classing Committee's
decision confirmed.

A.B.H.



© 2020

Lloyd's Register
Foundation