

as mid-line for length amidships...
ay of Engine and Boiler Spaces

„ Plate above floors, for length...
.. Intercostal Plate for length

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Steel S.S. "CABO ROCHE"* Rpt. *BBo* No. *6016*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

Before this case receives the consideration of the Committee, the Surveyors should be requested to state if they are correct in reporting that the Poop Deck Beams are fitted to every Frame; also whether the thickness of lower Deck Beams is as approved & not as stated and whether the thickness ^{after Peak} of Bulkhead plating & the stiffeners below lower Deck ~~are~~ on After Peak Bulkhead are as approved.

L BBo. 16/6/22



© 2020

Lloyd's Register
Foundation

004321-004325-0067

The Bull, or Channel

Angles on upper edge

Forecastle Deck Stringer Plate, b'dth & th'kns

Angles on ditto

130x76

166x80