

20 DEC 1966

LC Ship's name "NANCHANG"

Port

Auk. (a) 4 13134
Wln. (b) No. 11374

Last survey date 8.11.66

Class is subject to

No.4 hatchway coamings (p) on centre castle deck (temporarily repaired 9.66) being specially examined and dealt with as necessary by the S.S.

S.R.L. Appendix (as before ~~of 11/10/66~~)

Nature of present survey (afloat and in drydock)

(b) Temporary repairs to wasted plating.

(a) Temporary repairs to oil leakage into No.3 hold.

Recommendation

SUBJECT as above and to wasted No.2/3 hold and tween deck bulkheads in way of No.2 access trunkway being specially examined and dealt with as necessary by 12.66 and to No.3 aft air pipe (p) being specially examined and dealt with as

As Now. Subject. necessary by 2.67.

IN S.R.L. APPENDIX
(EXTENDED S.S.)

© 2020

11/12/66

R.F.L.

11/12/66

TO NOTE		
S. PLANS	S. RESEARCH	S. DEVELOP.
FREEBOARD	E. REPORTS	PUBS.