

"Area Enterprises"

The Owners should be informed that the ship will require to be opened up for the requirements of a full SS. to be carried out, as the Rotterdam Surveyors at their survey in 9/66 only carried out temporary repairs to place the ship in an efficient condition until the end of January 1967 and no items have been credited to the Special Survey.

JMB  
31/1/67

Cable Mla :-

" JHKg  
(Epl)

© 2020

Lloyd's Register  
Foundation

00436900473-0046