

Lloyd's Register of Shipping

16TH FLOOR P. & O. BUILDING

P. O. BOX 463

HONG KONG

15th March 1966

18 MAR 1966

X 871

Ans'd.....

The Secretary,
Lloyd's Register of Shipping,
LONDON.

Dear Sir,

S.S. "ASIA ENTERPRISES"

The Owners now write us as follows :-


" Due to repeated prolongation of loading, the vessel is still in Bitung/Menado range, North Celebes, Indonesia, and it is not possible to have the G.S. Pump and Windlass Block shipped there for installation onboard.

The only alternative is that we have ordered the vessel to call at Djakarta after completion of loading expected about end March, early April to have these G.S. Pump and Windlass Cylinder Block installed onboard under the supervision of your Agents. In this connection, please inform your Agents in Indonesia to contact our General Agents of the following address for exact schedule :

Mr. Moehardanus, Manager,
P.N. Djakarta Lloyd,
Djalan Pintu Besar Utara 18,
Djakarta-Kota.

We would also arrange, subject to availability of testing facilities, the Anchors tested simultaneously and we are arranging to purchase a replacement of the spare anchor here which we shall notify you in due course. "


Yours faithfully,



E.L. Green
For the Surveyors.

ELG:ncl

c.c. The Surveyor,
SOURABAYA.

For his attention and action.

Lloyd's Register
Foundation

004369-004373-0126

66
LSD

MEM LIMITS PER END 5.12.11.65 & 3.1.66
 DATES OF EXPIRY 10.65 & 11.65 extended until 2.66
 PROPOSED TO BE HELD end March or early April 1966
 (see this letter)

For proposed arrangements re subject (equip)
 see endt. 8.10.65 - see this letter

RSD
 24/3/66

24.3.66

Djakarta-Kota.
 Djaen Bunt Bessat 0421 19.
 B.M. Djakarta Lloyd
 Mr. Moehardjuna Manager.

for exact schedule:
 contact our General Agents of the following and
 connection please inform your Agents in Indonesia to
 on board under the supervision of your Agents. In this
 these G.S. Bunt and Mindiasa Cylinder Block installed
 loading expected about end March early April to have
 the vessel to call at Djakarta after completion of
 the only alternative is that we have ordered

on board.
 and Mindiasa Block shipped there for installation
 Indonesia, and it is not possible to have the G.S. Bunt
 vessel is still in Bitung/Wenago range, North Celebes.
 " Due to repeated prolongation of loading, the

The owners now write as follows :-

"G.S. 'ASIA ENTERPRISE'"

Dear Sir,

LONDON.
 Lloyd's Register of Shipping,
 The Secretary,

18 MAR 1966
 157 X

HOINC KOINC
 P.O. BOX 493
 10TH FLOOR P.O. BUILDING

Lloyd's Register of Shipping

CABLE ADDRESS: LLOYDS

TELEPHONE: 340046-7



© 2020
 Lloyd's Register
 Foundation

For the attention and action

SOURCE: AYU
 The Secretary

G.C.

FIG:NCI

For the Secretary
 E.I. Green