

Ship's Name SS/M/S/ "ADELPHOS PETRAKIS"

Gross tons 7170 Port of Registry Famagusta Port of Port Said

Date of build 6-44 Is there a rpt. 8? no Rpt. No. 7376

No. of visits First date Last date See Rpt. 9A
Interim Cert. issued & copy herewith? Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)

Date of completing rpt. Surveyed at, if different from Port above

Is a rpt. 9A attached? MN Nature of survey

Survey fees Damage fee Expenses

- See Rpt. 9 A -

S.A. fee

DOCKING

Propeller Sea connections Oil gland

Fastenings Wear down of stern bush (if relined, state clearance before and after)

Has screw/tube shaft been drawn? Date of examn.

Has shaft been changed? Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves adjusted to { Sat }
{ Spt }

Boiler securing arrangements

Main economisers

Steam heated steam generators

Forced circulating pumps

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Stb. 220 Lbs/□ " - 13.10.1966

Exhaust gas heated economisers and their safety valves

Steam generator safety valves adjusted to

Funnel

Were oil burning system & remote controls examined in accordance with rules?

I recommend that the machinery of this ship remain as classed with/without fresh record of

- See Rpt. 9 A -

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

(S. Fawzi)
Surveyor to Lloyd's Register of Shipping

THURSDAY 27 OCT 1966

See Rpt. 9A

004369-004373-0199

ALSO FOR

SPL FOR

TRO

SRL

POSTING


HEADER

CERT

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled, this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is



EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)	AUXILIARY
Total kW or kVA	Total kW or kVA
a Generators	Generators & governors
b Exciters	
c Air coolers	Motors for inboard O.F. service pump - good
d Motors	Switchboards & fittings
e Air coolers	Circuit breakers
f Control gear cables, etc.	Cables
g Insulation resistance	Insulation resistance
h Insulating oil test	Steering gear generators & motors
i Overspeed governors	Navigation light indicators
j Magnetic couplings	
k Air gap	

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC. (Wear and Tear)

Inboard O.F. service pump motor both end ball bearings renewed for wastage.

Stp. SSC lbs/2" - 13.10.1966

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.