

Ailsa Shipbuilding Co. Ltd., Troon.

Yard No. 448.

5c.9.45

1

X

Grantland

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME s.s. "EMPIRE CRUSOE" REPORT Gls. No. 70085

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

re of Survey First Entry. When due=

This vessel is similar to the "EMPIRE JESSICA" & "EMPIRE DIRK".

The tank top plating has been increased in thickness under the hatchways in lieu of ceiling.

100A1

1 Dk

*673t See Draw 9754 6/50
686t f.c.d. Plating 12.8.46*

Cell DB 268 1/2, wing tanks in mchy space 198t, FPT 110t, APT 117t
FK, 5BH, pt.Cem., Lloyd's A & CP

P 33' B 82' F 34'

O.L. 327.8'

u

1 11/16"



The class is assigned and maintained upon the understanding that the equipment ^{of Anchors} will be made to accord with the requirements of the Rules when the present state of emergency has passed, and that cargo battens will be fitted at the first available opportunity.

Insert in S.R.L:- (A bower anchor to be supplied).
Cargo battens to be fitted at the first opportunity.



f.c.d.
3.12.45. *[Signature]*

Lloyd's Register Foundation

004369 004373-0232