

GB Ship's name "SANTA KYRIAKI" Port Ams No. 27355

The class is subject to indented shell plate No.3 in 2nd below sheer (p.f) etc. being specially examined and dealt with as necessary next drydocking.

There is an S.R.L. Appendix Note.

See correspondence regarding stranding etc.

The AMSTERDAM Surveyors report (3,66), ship in dry dock and extensive damage noted due to grounding. The Surveyors point out that Owners state repairs are not being considered, and in agreement with Underwriters the ship has been declared a total loss and request the class be withdrawn.

IT IS THEREFORE SUBMITTED an appropriate notation be assigned.

*[Handwritten signature]*

16.5.66.

