

~~xxxxx~~

-2 AUG 1965

Ship's name "SANTA KYRIAKI" Port Cdz No. 3771

Class is subject to NONE Last survey date 20.6 65

~~fractured and buckled side plating,
deck plating and bulwarks in way of No. 2 cargo hold (p.s.)
being specially examined and dealt with as necessary
on ship's arrival at the River Tyne.~~

S.R.L. Appendix (as before ~~xxxxxxxx~~)

Nature of present survey (afloat ~~xxxxxxxxxxxxxxxx~~)

Examination of collision damage and temporary repairs.

Recommendation

SUBJECT to set in sheerstrake shell and deck stringer plating etc. and bulwarks etc. being specially examined and dealt with as necessary on ship's arrival at a U.K.port.

As Now. Subject

IN S.R.L. APPENDIX

(Sternframe solepiece (p.s) E.W. 8,58)
C.3 and D.2 (p.s. from fwd) indented.

NOTE:- This is a subsequent report of a previous survey -
for up to date minute see endorsement dated 22.7.65.