

17 DEC 1949

DCV

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME FIRMITY REPORT Lon. No. 119096

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This ship is classed BS* (Coasting Service).

A SPECIAL SURVEY TYPE 1, due 11.48, commenced Lon.5.48 (see B.C. list attached).

The LONDON Surveyors report (10.49) ship examined on slipway, bottom coated, the requirements of a SPECIAL SURVEY TYPE 1 complied with and, on account of wear and tear, a few repairs effected.

The main engine seating has now been modified to suit new engine installed at this time. The seating is in accordance with plans previously approved for this class of ship.

IT IS SUBMITTED this ship is worthy to remain as classed by the British Corporation, with record of docking 9.49, and to have notations of "ss. Lon.- 10.49" and "Annual Survey 10.49".

BS* (Coasting Service)
9.49 Lon.
ss. Lon.- 10.49
Annual Survey 10.49



© 2009
22
11
11.49

Lloyd's Register
Foundation

004374-004381-0234