

Dear Mr. Clement,

I return herewith the papers on the "BRIGHTON"

Lith

Brighton Lith no 21027 Superheaters  
are not fitted on this vessel Its no 21672 is  
incorrect

Surs

Thomas W. Clement  
18/10/43.

© 2021

Lloyd's Register  
Foundation

5  
R. J. L.  
18/10/43

004387-004393-0248

you would prefer to have this dealt with in London.

(Ltr. 5.)

- 8 SEP 1941

6 SEP 1947

*Port of*

**SUNDERLAND**

The following Reports are enclosed :—

NAME OF VESSEL.	No. of Report.	State whether the Reports are on Hull or Machinery, or both; and if on Hull only, state whether and when one on Machinery will be sent.	State whether the Report is a Final Report.
Josewyn	33192	Hull and Machinery	cr
		m	

© 2021

Lloyd's Register  
Foundation

N.B.—This form is to be used for the advice of reports only.

40m.3.39. (MADE AND PRINTED IN ENGLAND)